
FORM MR-AR (Revised 1/91)

I.



DIVISION OF OIL GAS & MINING

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING 355 West North Temple 3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

GENE	ERAL INFORMATION
1.	Report Time Period: From (mo./yr.) Jan. 1,91To (mo./yr.) Dec.31,91
2.	DOGM File Number: s/015/060
3.	Mine Name: Range Creek Project
4.	Mineral(s) Mined: Gold and Mercury
5.	Legal Description (Location of Lands Affected):
	NW 1/4, SW 1/4, Section 36 /, Township 17 S., Range 16 E. SLB&M
	1/4,1/4, Section, Township, Range
	1/4,1/4, Section, Township, Range
6.	Name of Operator or Company: Range Creek Mines, Ltd.
7.	Permanent Address: <u>c/o George D. Fehr</u>
	10 Exchange Place, Suite 610
	Salt Take City IItah 84111

Name: George D. Fehr Title: General Partner Address: 10 Exchange Place, #610, Salt Lake City, UT 84 Phone: (801) 363-5893 Please check if any of the above information has changed since previous year. MINING AND RECLAMATION Was the mine active during the past year? Yes No If active, how much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. When the small amount of material was taken, the surface	Con	npany Representative (or designated operator):			
Address: 10 Exchange Place, #610, Salt Lake City, UT 84 Phone: (801) 363-5893 Please check if any of the above information has changed since previous year. MINING AND RECLAMATION Was the mine active during the past year? Yes No II If active, how much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.		Name: George D. Fehr			
Phone: (801) 363-5893 Please check if any of the above information has changed since previous year. MINING AND RECLAMATION Was the mine active during the past year? Yes No If active, how much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.		Title: General Partner			
□ Please check if any of the above information has changed since previous year. MINING AND RECLAMATION Was the mine active during the past year? Yes □ No ☒ If active, how much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.		Address: 10 Exchange Place, #610, Salt Lake City, UT 84			
MINING AND RECLAMATION Was the mine active during the past year? Yes □ No ☒ If active, how much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.		Phone: (801) 363-5893			
Was the mine active during the past year? Yes No Market Now much ore or mineral was mined? Only Samples How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.		•			
How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	MIN	VING AND RECLAMATION			
How much new or additional acreage was affected during past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	Was	s the mine active during the past year? Yes \(\square \) No \(\overline{\mathbb{Z}} \)			
Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	If a	ctive, how much ore or mineral was mined?Only Samples			
during the past year. This description should include the type of work performed, and volume of material moved. Samples taken. Shoveled from surface. Total Volume: 2 Tons How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	Ног	How much new or additional acreage was affected during past year? <u>None</u>			
How much acreage was reclaimed during past year? None Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	dur	ing the past year. This description should include the type of work			
Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	Sar	nples taken. Shoveled from surface. Total Volume: 2 Tons			
Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.					
Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.	***************************************				
description should include methods employed, and an evaluation of the results.	юН	w much acreage was reclaimed during past year? None			
when the small amount of material was taken, the surface	dese resu	cription should include methods employed, and an evaluation of the ults.			
of the land was not manned. As smallestice of the tration					
of the land was not scarred. An evaluation of the testing showed considerable promise. Operations are planned.					

- 7. What is the total disturbed acreage at years end? None, other than about 20 square feet, but no scars were left.
- 8. Briefly summarize mining and reclamation planned for the upcoming year.

 It is estimated that at least 500 to 2,000 tons will be mined in 1992. No more than one acre will be disturbed. If operations on the acre are continuing, reclamation will be postponed until a large enough area is disturbed and ore depleted to justify reclamation activity.

On the other hand, if ore is depleted or the project is terminated, reclamation will immediately be undertaken to restore the premises.

NOTE:

Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

- 1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
- 2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Range Creek Mines, Ltd.

Title of Operator: George D. Fehr

Signature of Operator: Design W. Town

Date: February 12, 1992

jb MR-AR